

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Ford C-Max 1.0 EcoBoost 125 Titanium 5dr

Inspection Serious Damage? No		Vehicle			nama
		VAT	Margin		
		V5	Present		
Details					
Reg. date	11/10/2017	Keys	2	CAP Clean	£3,050.00
Year	2017	Service history	Yes	CAP Average	£2,550.00
Mileage	100,125 Miles Warranted	Service documents	Service Book	CAP Below	£2,075.00
		Number of stamps	7	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	18/11/2024	Gears	6
Colour	SILVER	Last service miles	93,354		
VIN	WF0VXXGCEVHC58223		10/10/2025		
Body Style	MPV				

Last Service - 18.11.2024 at 93354 miles (7 main dealer services)

Tyres			
NSF	BUDGET	4.0mm	
NSR	BUDGET	4.0mm	
OSF	BUDGET	3.0mm	
OSR	BUDGET	4.0mm	
Spare			

Features

Bluetooth connection

- Rear wiper
- Body coloured bumpers
- Folding rear seats
 Rear electric windows
- ABS
- Traction control
- · Cloth seat trim

- Cruise control
- Steering wheel mounted controls Electric door mirrors Air conditioning ٠ ٠
- •

٠

- Front armrest Rear headrests ٠
- Drivers airbag Tyre pressure monitor
- Alloy wheels
- PAS

 - Air conditioning
 Front electric windows

 - Metallic Paint
 - Isofix child seat anchor points
 - Central locking
- Rear parking sensorDigital radio
- Climate control
- . Front head restraints .
- 3x3 point rear seat belts
- Passenger airbag
 Remote central locking

Photos






















Condition Check



Damage Photos





2: Bumper Front Chipped Multiple Chips

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Over 50mm

No Image

No Image

5: Door nsf Scratched Over 25mm Not Thru Paint 6: Door nsr Scratched Over 25mm Not Thru Paint

No Image

7: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



8: Bumper Rear Scratched 25 to 100mm Thru Paint

No Image

No Image

9: Bumper Rear Scratched Over 25mm Not Thru Paint



10: Boot Lid Scratched Over 25mm Not Thru Paint

No Image

12: Door osr Scratched Over 25mm Not Thru Paint

11: Wheel osr Scratched Up To 50mm

No Image

13: Door osf Scratched Over 25mm Not Thru Paint

Interior



14: Wheel osf Scratched Over 50mm

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK