



VEHICLE INSPECTION REPORT

DV60XCL

Toyota Avensis 2.0 D-4D T4 Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/11/2010	Body Style	Estate	CAP Clean	£1,500.00
Year	2010	Keys	2	CAP Average	£1,100.00
Mileage	122,569 Miles Warranted	Service history	Yes	CAP Below	£700.00
Fuel Type	Diesel	Number of stamps	13	Gearbox	MANUAL
Colour	GREY	Last service miles	115,895	Gears	6
VIN	SB1ED76L20E053424	MOT Due	17/10/2025		

Last Service: 22/11/2024 at 115895 miles. (13 services)

Tyres

NSF	NANKANG	4.0mm
NSR	BRIDGESTONE	Worn
OSF	NANKANG	3.0mm
OSR	BRIDGESTONE	2.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Navigation system
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Dented
Over 2 UpTo 10mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Wheel osr
Scratched
Over 50mm

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Dented
Between 10mm + 30mm

No Image

18: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Wheel osf
Scratched
Over 50mm

No Image

20: Tyre nsr
Worn
Replace

No Image

21: Tyre nsr
Worn
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK