



VEHICLE INSPECTION REPORT

GY69LFO

Nissan Qashqai 1.3 DiG-T 160 Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/10/2019	Keys	1	CAP Clean	£10,750.00
Year	2019	Service history	Yes	CAP Average	£9,550.00
Mileage	54,268 Miles Warranted	Service documents	Service Book	CAP Below	£8,375.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLACK	Last service date	21/10/2021	Gears	6
VIN	SJNFFAJ11U2705218	Last service miles	13,396	Doors	5
Body Style	Hatchback	MOT Due	26/09/2025		

Last Service - 21.10.2021 at 13396 miles (2 main dealer services)

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Between 10mm + 30mm



6: Door nsf
Chipped
1 To 5

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Chipped
Multiple Chips

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Dented
Over 2 UpTo 10mm

No Image

14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Up To 50mm

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Dented
Over 30mm

No Image

18: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Wheel osf
Scratched
Up To 50mm

No Image

20: Door osr
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		