



VEHICLE INSPECTION REPORT

GU05LCY

Skoda Fabia 1.9 TDI PD Elegance 5dr [AC]

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 31/03/2005

Year 2005

Mileage 93,745 Miles
Warranted

Fuel Type Diesel

Colour BEIGE

VIN TMBMS46Y254322350

Body Style Hatchback

Keys 1

Service history Yes

Service documents Service Book

Number of stamps 1

Last service date 17/11/2016

Last service miles 63,645

MOT Due Expired

CAP Clean £610.00

CAP Average £270.00

CAP Below £200.00

Gearbox MANUAL

Gears 5

Doors 5

£65 ADDITIONAL FEE

Last Service - 17.11.2016 at 63645 miles (1 services)

MOT Expired

Boot doesn't open and headlights cloudy

Tyres

NSF BUDGET 2.0mm

NSR RAPID 4.0mm

OSF BUDGET 3.0mm

OSR RAPID 3.0mm

Spare

Features


- Rear wiper
- Air conditioning
- Metallic Paint
- Central locking
- Radio/CD
- Climate control
- ABS
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Dented
Over 2 UpTo 10mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint




7: Door nsr
Chipped
1 To 5

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




11: Wheel nsr
Scratched
Over 50mm



12: Sill ns
Dented
With Paint Damage



13: Bumper Rear
Chipped
Multiple Chips



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

15: Boot Lid
Scratched
Over 25mm Not Thru Paint



16: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

No Image

17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




18: Wheel osr
Scratched
Over 50mm



19: Door osr
Dented
Over 30mm



20: Door osf
Dented
Over 2 UpTo 10mm



21: Sill os
Rusted
UpTo 5mm



22: Wing osf
Dented
Over 30mm



23: Wheel osf
Scratched
Over 50mm



24: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK