

VEHICLE INSPECTION REPORT

GV22LFP

Volkswagen Id.3 110kW Life Pure Performance 45kWh 5dr Auto

inspection		venicie			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present		
Details					
Reg. date	28/07/2022	Keys	1	CAP Average	£9,350.00
Year	2022	Service history	Yes	CAP Below	£8,300.00
Mileage	45,760 Miles Warranted	Service documents	Printout	Gearbox	AUTOMATIC
Fuel Type	Electric	Number of stamps	1	Gears	1
Colour	GREY	Last service date	12/06/2025	Doors	5
VIN	WVWZZZE1ZNP034208	Last service miles	45,760		
Body Style	Hatchback	CAP Clean	£10,450.00		

£65 ADDITIONAL FEE LAST SERVICE 12/6/25 @ 45760 MILES (1 MAIN DEALER)

Tyres			
NSF	HANKOOK	3.0mm	
NSR	HANKOOK	2.0mm	
OSF	HANKOOK	3.0mm	
OSR	CONTINENTAL	3.0mm	
Spare			

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- · Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Steel wheels

Photos












Condition Check



Damage Photos



1: Bumper Front Scratched 25 to 100mm Thru Paint No Image

2: Bumper Front Scratched Over 25mm Not Thru Paint

No Image

3: Wing nsf Scratched Over 25mm Not Thru Paint



4: Door nsf Scratched Over 25mm Thru Paint

No Image

5: Door nsr Scratched Over 25mm Not Thru Paint



6: Bumper Rear Scratched 25 to 100mm Thru Paint

No Image

7: Bumper Rear Scratched Over 25mm Not Thru Paint

No Image

8: Door osr Scratched Over 25mm Not Thru Paint

No Image

9: Door osf Scratched Over 25mm Not Thru Paint



10: Door Mirror Assy osf Broken Replace

No Image

11: Wing osf Scratched Over 25mm Not Thru Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	ОК
Sat nav	OK	Steering	OK