

#### 46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

## **VEHICLE INSPECTION REPORT**

**GY71HRM** 

### Ford Kuga 2.5 PHEV ST-Line X Edition 5dr CVT

Inspection Serious Damage? No		Vehicle			nama
		VAT	Margin		
		V5	Present		
Details					
Reg. date	01/12/2021	Keys	2	CAP Clean	£16,550.00
Year	2021	Service history	Yes	CAP Average	£15,200.00
Mileage	38,691 Miles Warranted	Service documents	Printout	CAP Below	£13,850.00
Fuel Type	Hybrid Electric	Number of stamps	1	Gearbox	CVT
Colour	WHITE	Last service date	02/05/2023	Gears	1
VIN	WF0FXXWPMHMC67880	Last service miles	18,049	Doors	5
Body Style	Hatchback	MOT Due	30/11/2025		
,					

£65 ADDITIONAL FEE. Service confirmed by Hendy Horsham. Last Service: 02/05/2023 at 18049 miles. (1 main dealer service)

Tyres			
NSF	CONTINENTAL	4.0mm	
NSR	CONTINENTAL	5.0mm	
OSF	CONTINENTAL	4.0mm	
OSR	CONTINENTAL	5.0mm	
Spare			

### Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
  Leather seat trim
- Cruise control
- ٠ Park assist camera ٠
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking Alloy wheels

- Front parking sensor
- Rear parking sensor Body coloured bumpers ٠
- ٠
- Electrically adjustable drivers seat 
   Front armrest Rear headrests
- Passenger airbag
  Remote central locking
- · Heated front seat
- Rear wiper
  Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim

#### Photos










## **Condition Check**



### Damage Photos





1: Bonnet Chipped 1 To 5

2: Bumper Front Chipped Multiple Chips

# No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Up To 50mm

# No Image

# No Image

5: Door nsf Scratched Over 25mm Not Thru Paint 6: Door nsr Scratched Over 25mm Not Thru Paint



7: Bumper Rear Chipped Multiple Chips

# No Image

8: Bumper Rear Scratched Over 25mm Not Thru Paint

# No Image

9: Door osr Scratched Over 25mm Not Thru Paint



11: Wheel osf Scratched Up To 50mm

#### Interior

Carpet Condition	
Seat Condition	

Average Average Upholstery Condition Odour

Cracked

Replace

Average No

#### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs 0	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting 0	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake 0	OK	No Excessive Smoking	OK



10: Door osf Dented 2 Or Less UpTo 10mm



EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	ОК
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		