



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**VE21XUX**

## Inspection

Serious Damage? No

## Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

## Details

Reg. date	11/06/2021	Keys	2	CAP Clean	£17,800.00
Year	2021	Service history	Yes	CAP Average	£16,450.00
Mileage	26,065 Miles Warranted	Service documents	Printout	CAP Below	£15,100.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	SEMI AUTO
Colour	ORANGE	Last service date	09/08/2023	Gears	7
VIN	WVGZZZC1ZMY084106	Last service miles	15,588	Doors	5
Body Style	Hatchback	MOT Due	10/06/2026		

£65 ADDITIONAL FEE LAST SERVICE 9/8/23 @ 15588 MILES ( 1 SERVICE)

## Tyres

NSF	HANKOOK	Damaged
NSR	HANKOOK	4.0mm
OSF	HANKOOK	4.0mm
OSR	HANKOOK	4.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim

## Photos







## Condition Check



## Damage Photos



1: Tyre nsf  
Damaged  
Replace



2: Bonnet  
Chipped  
1 To 5






3: Bumper Front  
Chipped  
Multiple Chips




4: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Scratched  
UpTo 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint




8: Door nsr  
Chipped  
1 To 5



9: Wheel nsr  
Scratched  
Over 50mm




10: Qtr Panel Trim ns  
Scuffed  
Over 25mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




14: Wheel osr  
Scratched  
Up To 50mm






15: Door osr  
Dented  
Over 30mm




16: Door osf  
Dented  
2 Or Less UpTo 10mm



17: Door osf  
Scratched  
Over 25mm Not Thru Paint



18: Wheel osf  
Scratched  
Up To 50mm



19: Tyre nsf  
Damaged  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK