



VEHICLE INSPECTION REPORT

KM06MAZ

Nissan Navara DCI OUTLAW 4X4 SHR SWB DCB

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/07/2006	Body Style	Pick-up	Last service miles	153,156
Year	2006	Keys	1	MOT Due	04/12/2025
Mileage	155,828 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	1
Colour	BLACK	Number of stamps	16	Doors	5
VIN	VSKCVND40U0111493	Last service date	03/12/2024		

LAST SERVICE 3/12/24 @ 153156 MILES (16 SERVICES 3 MAIN DEALER) BOOK AND PRINT Squeaking noise while driving

Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Rear electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Dented
With Paint Damage




3: Qtr Panel osr
Dented
With Paint Damage



4: Wheel osr
Scratched
Over 50mm




5: Door osr
Chipped
1 To 5



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Door osf
Dented
Between 10mm + 30mm



8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Wheel osf
Scratched
Over 50mm




10: Wing osf
Poor Previous Repair
Poor Paint




11: Bumper Front
Poor Previous Repair
Poor Paint



12: Bonnet
Chipped
1 To 5




13: Bonnet
Scratched
Over 25mm Not Thru Paint




14: Wing nsf
Scratched
Over 25mm Not Thru Paint



15: Door nsf
Dented
Between 10mm + 30mm



16: Door nsf
Scratched
UpTo 25mm Not Thru Paint



17: Door nsr
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel nsr
Poor Previous Repair
Poor Paint



19: Wheel nsr
Scratched
Over 50mm




20: Roof
Dented
With Paint Damage



21: Seat Base Cover osf
Torn
Over 3mm



22: Handle Inner nsf
Damaged
Replace



23: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK