



VEHICLE INSPECTION REPORT

KR14ADO

Nissan Qashqai 1.2 DiG-T Acenta Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/05/2014	Keys	2	CAP Clean	£3,075.00
Year	2014	Service history	Yes	CAP Average	£2,575.00
Mileage	85,150 Miles Warranted	Service documents	Service Book	CAP Below	£2,075.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	BLACK	Last service date	12/11/2024	Gears	6
VIN	SJNFEAJ11U1087221	Last service miles	79,501	Doors	5
Body Style	Hatchback	MOT Due	27/08/2025		

Last service 12/11/2024 @ 79501 miles (10 SERVICES 3 MAIN DEALER) Engine rattles when revved

Tyres

NSF	BRIDGESTONE	2.0mm
NSR	BRIDGESTONE	3.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint




7: Door nsr
Chipped
1 To 5

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Chipped
1 To 5

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Over 2 UpTo 10mm

No Image

18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Door osf
Scratched
Over 25mm Thru Paint

No Image

20: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		