



# VEHICLE INSPECTION REPORT

**KM12YJU**

## Seat Exeo 2.0 TDI CR SE Tech 5dr [143]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	23/05/2012	Keys	2	CAP Clean	£1,150.00
Year	2012	Service history	Yes	CAP Average	£750.00
Mileage	157,664 Miles Warranted	Service documents	Service Book	CAP Below	£350.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	MANUAL
Colour	BLACK	Last service date	15/01/2020	Gears	6
VIN	VSSZZZ3RZCR013858	Last service miles	106,786		
Body Style	Estate	MOT Due	05/02/2026		

Last service 15/01/2020 @ 106786 miles (4 SERVICES 2 MAIN DEALER)

### Tyres

NSF	TRIANGLE	2.0mm
NSR	RAPID	3.0mm
OSF	RAPID	3.0mm
OSR	RAPID	3.0mm
Spare		

## Features


- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Poor Paint



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Chipped  
1 To 5

No Image



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel nsr  
Dented  
With Paint Damage




10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Boot Lid  
Chipped  
1 To 5



13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



14: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint





15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Door osf  
Chipped  
1 To 5



18: Door osf  
Scratched  
Over 25mm Not Thru Paint



19: Door Mirror Assy osf  
Broken  
Replace



20: Wing osf  
Chipped  
1 To 5

No Image



21: Wing osf  
Scratched  
Over 25mm Not Thru Paint

22: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK