



VEHICLE INSPECTION REPORT

SJ11YJB

Seat Ibiza 1.2 TDI CR Ecomotive SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2011	Keys	1	CAP Clean	£570.00
Year	2011	Service history	Yes	CAP Average	£210.00
Mileage	151,888 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	10	Gearbox	MANUAL
Colour	BLACK	Last service date	13/03/2023	Gears	5
VIN	VSSZZZ6JZBR099443	Last service miles	130,316	Doors	5
Body Style	Hatchback	MOT Due	26/03/2026		

£100 ADDITIONAL FEE. LAST SERVICE 13/3/23 @ 130316 MILES (10 SERVICES 6 MAIN DEALER) BOOK AND PRINT
INPUT ERROR ON MOT HISTORY IN 2020

Tyres

NSF	HANKOOK	3.0mm
NSR	BUDGET	2.0mm
OSF	CONTINENTAL	3.0mm
OSR	BUDGET	OK
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bonnet
Scratched
Over 25mm Not Thru Paint



3: Screen Front
Chipped
UpTo 10mm




4: Bumper Front
Poor Previous Repair
Poor Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Wing nsf
Scratched
Over 25mm Not Thru Paint




8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsf
Dented
With Paint Damage



10: Door nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Dented
Over 30mm




16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Chipped
1 To 5



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK