



VEHICLE INSPECTION REPORT

GU10CYS

Nissan Qashqai+2 1.5 dCi N-Tec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/03/2010	Keys	2	CAP Clean	£1,725.00
Year	2010	Service history	Yes	CAP Average	£1,325.00
Mileage	81,641 Miles Warranted	Service documents	Service Book	CAP Below	£925.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	MANUAL
Colour	BLACK	Last service date	09/02/2024	Gears	6
VIN	SJNJCAJ10U7003362	Last service miles	74,201	Doors	5
Body Style	Hatchback	MOT Due	07/03/2026		

LAST SERVICE 9/2/24 @ 74201 MILES (9 MAIN DEALER) BOOK Rear camera fault

Tyres

NSF	MAXTREK	4.0mm
NSR	MAXTREK	4.0mm
OSF	MAXTREK	4.0mm
OSR	MAXTREK	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Park assist camera
- Audio remote control
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Door Pad osf
Torn
Over 10mm



2: Seat Base Cover osf
Torn
UpTo 3mm



3: Seat Back Cover osf
Torn
Over 3mm




4: Wing osf
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osr
Scratched
UpTo 25mm Thru Paint



8: Door osr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate
Dented
With Paint Damage



12: Wheel nsr
Scratched
Up To 50mm



13: Door nsr
Dented
Over 30mm



14: Door nsf
Scratched
Over 25mm Thru Paint



15: Wing nsf
Scratched
Over 25mm Thru Paint



16: Wheel nsf
Scratched
Over 50mm



17: Bumper Front
Scratched
25 to 100mm Thru Paint



18: Bonnet
Scratched
Over 25mm Thru Paint



19: Qtr Panel nsr
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Poor
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		