



VEHICLE INSPECTION REPORT

SG16NVK

Jeep Renegade 1.6 Multijet Limited 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/05/2016	Keys	1	CAP Clean	£4,125.00
Year	2016	Service history	Yes	CAP Average	£3,525.00
Mileage	85,865 Miles Warranted	Service documents	Service Book	CAP Below	£2,925.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	MANUAL
Colour	BLACK	Last service date	15/02/2025	Gears	6
VIN	1C4BU0000GPD37826	Last service miles	83,020		
Body Style	Estate	MOT Due	04/06/2026		

Last Service: 15/02/2025 at 83020 miles. (4 services). Book & print. Eml on

Tyres


NSF	BUDGET	3.0mm
NSR	BRIDGESTONE	2.0mm
OSF	BUDGET	3.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

3: Boot Lid
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel osr
Chipped
1 To 5

No Image

5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Wheel osr
Scratched
Over 50mm




7: Door osr
Chipped
1 To 5

No Image


8: Door osr
Scratched
Over 25mm Not Thru Paint



9: Door osf
Chipped
1 To 5




10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Wing osf
Scratched
Over 25mm Not Thru Paint



12: Wheel osf
Scratched
Over 50mm



13: Bonnet
Chipped
Multiple Chips



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Wheel nsf
Scratched
Over 50mm



16: Wing nsf
Chipped
1 To 5




17: Wing nsf
Scratched
Over 25mm Not Thru Paint



18: Door nsf
Dented
With Paint Damage



19: Door nsr
Chipped
1 To 5



20: Door nsr
Scratched
Over 25mm Not Thru Paint



21: Wheel nsr
Scratched
Over 50mm



22: Qtr Panel nsr
Chipped
1 To 5



23: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK