

VEHICLE INSPECTION REPORT

LV57ZFF

Vauxhall Astra 1.7 CDTi 16V Design [100] 5dr

inspection		venicie			nama
Serious Damage?	No	VAT	Margin		Sade 9
		V5	Present		
Details					
Reg. date	30/11/2007	Body Style	Estate	CAP Average	£390.00
Year	2007	Number of stamps	10	CAP Below	£200.00
Mileage	95,000 Miles Warranted	Last service date	11/07/2022	Gearbox	MANUAL
		Last service miles	91,825	Gears	5
Fuel Type	Diesel	MOT Due	27/10/2025		
Colour	SILVER	CAP Clean	£770.00		
VIN	W0L0AHL3582072390		<u> </u>		

LAST SERVICE 11-07-2022 @91825 MILES (3 SERVICES IN BOOK)

Ţ	yr	es
---	----	----

NSF	BUDGET	4.0mm	
NSR	BUDGET	3.0mm	
OSF	LAUFENN	4.0mm	
OSR	RAPID	5.0mm	
Spare			

Features

- PAS
- Radio/CD
- Climate control
- · Rear electric windows
- ABS
- Central locking
- Rear wiper Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag Remote central locking
- Steering wheel mounted controls
 Electric door mirrors
 Audio remote control
 Air conditioning
- Front head restraints
 Metallic Paint
- Isofix child seat anchor points
 Partial leather seat trim

- Audio remote control
 Air conditioning
 Height adjustable drivers seat
 3x3 point rear seat belts
- Passenger airbagAlloy wheels

Photos













Eastbourne Car Auctions










Condition Check



Damage Photos

No Image

1: Boot Lid Scratched Over 25mm Not Thru Paint



2: Bumper Rear Scratched Over 100mm Thru Paint



3: Qtr Panel osr Dented Over 30mm



4: Wheel osr Scratched Over 50mm



5: Door osr Poor Previous Repair Poor Paint



6: Door osf Dented With Paint Damage



7: Roof Poor Previous Repair Paint Flake



8: Wing osf Poor Previous Repair Poor Paint



9: Wheel osf Scratched Over 50mm



10: Bonnet Chipped 1 To 5



11: Bumper Front Dented With Paint Damage



12: Wing nsf Chipped 1 To 5



13: Wheel nsf Scratched Over 50mm




14: Door nsf Dented 2 Or Less UpTo 10mm

No Image

No Image

15: Door nsf Scratched Over 25mm Not Thru Paint





17: Qtr Panel nsr Scratched Over 25mm Thru Paint



18: Seat Base Cover osf Torn Over 3mm



19: Seat Base Cover nsf Torn UpTo 3mm



20: Headlamp os Broken Replace

Interior

Carpet Condition Seat Condition

Average Poor Upholstery Condition Odour

Average No