



# VEHICLE INSPECTION REPORT

**GY10FRR**

## Vauxhall Astra 1.4i 16V Exclusiv 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	19/03/2010	Keys	2	CAP Clean	£900.00
Year	2010	Service history	Yes	CAP Average	£500.00
Mileage	85,378 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	BLUE	Last service date	25/11/2024	Gears	5
VIN	W0LPD6EB4A8051499	Last service miles	82,124	Doors	5
Body Style	Hatchback	MOT Due	Expired		

LAST SERVICE 25-11-2024 @82124 MILES (5 SERVICES BOOK & PRINT) Squeaky belt


Tyres		
NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	NEXEN	4.0mm
OSR	AUTOGRIP	4.0mm
Spare		

## Features


- Bluetooth connection
  - Steering wheel mounted controls
  - Electric door mirrors
  - Front head restraints
  - 3x3 point rear seat belts
  - Passenger airbag
  - Remote central locking
- Cruise control
  - Audio remote control
  - Air conditioning
  - Height adjustable drivers seat
  - ABS
  - Side airbags
  - Cloth seat trim
- PAS
  - Radio/CD
  - Climate control
  - Rear headrests
  - Drivers airbag
  - Traction control
  - Alloy wheels
- Rear wiper
  - Body coloured bumpers
  - Front electric windows
  - Solid Paint
  - Isofix child seat anchor points
  - Central locking

## Photos





Condition Check



Damage Photos



1: Other  
N/A  
N/A



2: Bonnet  
Chipped  
1 To 5





3: Bumper Front  
Scratched  
Over 100mm Thru Paint




4: Wheel nsf  
Scratched  
Over 50mm




5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsf  
Chipped  
1 To 5



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Chipped  
1 To 5

No Image

9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



10: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm

No Image

11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Wheel nsr  
Scratched  
Up To 50mm



13: Bumper Rear  
Dented  
With Paint Damage


No Image

14: Boot Lid  
Scratched  
Over 25mm Not Thru Paint





15: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm




16: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint




17: Wheel osr  
Scratched  
Over 50mm



18: Door osr  
Dented  
Over 2 UpTo 10mm




19: Door osr  
Scratched  
Over 25mm Not Thru Paint



20: Door osf  
Scratched  
Over 25mm Thru Paint



21: Wing osf  
Chipped  
1 To 5



22: Wing osf  
Scratched  
Over 25mm Not Thru Paint



23: Wheel osf  
Scratched  
Over 50mm



24: Roof  
Scratched  
Over 25mm Not Thru Paint

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK