



# VEHICLE INSPECTION REPORT

**HV07OKD**

## Toyota Yaris 1.3 VVT-i Zinc 5dr MMT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	16/03/2007	Keys	2	CAP Average	£1,450.00
Year	2007	Service history	Yes	CAP Below	£1,000.00
Mileage	80,767 Miles Warranted	Number of stamps	17	Gearbox	SEMI AUTO
Fuel Type	Petrol	Last service date	18/01/2024	Gears	4
Colour	SILVER	Last service miles	70,961	Doors	5
VIN	VNKKL96340A155996	MOT Due	08/02/2026		
Body Style	Hatchback	CAP Clean	£1,875.00		

### Tyres

NSF	LAUFENN	4.0mm
NSR	BUDGET	4.0mm
OSF	LAUFENN	4.0mm
OSR	MICHELIN	4.0mm
Spare		

## Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door Mirror Assy nsf  
Broken  
Replace



6: Door nsf  
Chipped  
Multiple Chips



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Dented  
With Paint Damage





9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Boot Lid  
Dented  
Over 30mm



12: Lamp osr  
Broken  
Replace



13: Qtr Panel osr  
Dented  
With Paint Damage




14: Wheel osr  
Scratched  
Over 50mm



15: Door osr  
Dented  
Over 30mm



16: Door osf  
Chipped  
1 To 5



17: Door osf  
Scratched  
Over 25mm Not Thru Paint



18: Door Mirror Assy osf  
Broken  
Replace



19: Wing osf  
Chipped  
1 To 5



20: Bonnet  
Dented  
2 Or Less UpTo 10mm

## Interior



**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK