



# VEHICLE INSPECTION REPORT

**EO64XFA**

## Kia Rio 1.4 2 5dr Auto

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
4

### Details

Reg. date 26/09/2014

Year 2014

Mileage 97,171 Miles  
Warranted

Fuel Type Petrol

Colour RED

VIN KNADN512ME6912624

Body Style Hatchback

Keys 1

Service history Yes

Service documents Service Book

Number of stamps 4

Last service date 31/08/2021

Last service miles 68,168

MOT Due 23/11/2025

CAP Clean £2,625.00

CAP Average £2,175.00

CAP Below £1,725.00

Gearbox AUTOMATIC

Gears 4

Doors 5

£100 ADDITIONAL FEE, LAST SERVICE 31-08-2021 @68168 MILES (4 SERVICES)

### Tyres

NSF BUDGET 4.0mm

NSR BUDGET 2.0mm

OSF BUDGET 4.0mm

OSR BUDGET 2.0mm


Spare

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips





3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5




6: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



7: Door nsf  
Dented  
Over 30mm



8: Door nsr  
Dented  
Over 30mm




9: Qtr Panel nsr  
Chipped  
1 To 5



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Boot Lid  
Dented  
Over 30mm



14: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint




No Image

15: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint




16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Dented  
Over 2 UpTo 10mm

No Image

18: Door osr  
Scratched  
Over 25mm Not Thru Paint



19: Door osf  
Dented  
Over 2 UpTo 10mm

No Image

20: Door osf  
Scratched  
Over 25mm Not Thru Paint



21: Door Mirror Assy osf  
Broken  
Replace



22: Wing osf  
Chipped  
1 To 5



23: Wheel osf  
Scratched  
Over 50mm



24: Screen Front  
Chipped  
UpTo 10mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

### Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK