



# VEHICLE INSPECTION REPORT

**KD19FBG**

## Nissan Qashqai 1.3 DiG-T N-Motion 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	28/06/2019	Keys	2	CAP Clean	£11,550.00
Year	2019	Service history	Yes	CAP Average	£10,300.00
Mileage	32,528 Miles Warranted	Service documents	Service Book	CAP Below	£9,125.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	SILVER	Last service date	04/03/2024	Gears	6
VIN	SJNFFAJ11U2603750	Last service miles	28,516	Doors	5
Body Style	Hatchback	MOT Due	21/07/2025		

Last Service: 04/03/2024 at 28516 miles. (4 services (3 main dealer) ) Starting fault/rough idle  
Eml on

### Tyres


NSF	MICHELIN	3.0mm
NSR	HIFLY	4.0mm
OSF	MICHELIN	2.0mm
OSR	MICHELIN	Worn
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm

No Image

No Image

5: Door nsf  
Scratched  
Over 25mm Not Thru Paint

6: Door nsr  
Scratched  
Over 25mm Not Thru Paint

No Image




7: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

8: Wheel nsr  
Scratched  
Over 50mm



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint




10: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



11: Wheel osr  
Scratched  
Up To 50mm



12: Door osr  
Scratched  
Over 25mm Not Thru Paint




13: Door osf  
Scratched  
Over 25mm Not Thru Paint



14: Wing osf  
Scratched  
Over 25mm Not Thru Paint



15: Wheel osf  
Scratched  
Over 50mm



16: Tyre osr  
Worn  
Replace



17: Tyre osr  
Worn  
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		