



VEHICLE INSPECTION REPORT

GV15FRD

Mazda 6 2.2d Sport Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	27/06/2015	Keys	2	CAP Clean	£3,550.00
Year	2015	Service history	Yes	CAP Average	£3,025.00
Mileage	80,156 Miles Warranted	Service documents	Printout	CAP Below	£2,500.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	MANUAL
Colour	BLACK	Last service date	26/01/2024	Gears	6
VIN	JMZGJ691621185023	Last service miles	74,636		
Body Style	Estate	MOT Due	10/06/2026		

Last Service: 26/01/2024 at 74636 miles. (6 main dealer services)

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	DUNLOP	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osr
Chipped
1 To 5




3: Qtr Panel osr
Chipped
1 To 5




4: Wheel osr
Scratched
Over 50mm



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Bumper Rear
Chipped
Multiple Chips



7: Other
N/A
N/A



8: Wheel nsr
Scratched
Over 50mm



9: Door nsf
Chipped
Edge Chip




10: Door nsf
Chipped
1 To 5




11: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Poor Previous Repair
Paint Flake



14: Bonnet
Chipped
1 To 5



15: Wing nsf
Poor Previous Repair
Poor Paint



16: D Post ns
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK