



VEHICLE INSPECTION REPORT

FV58LNY

Vauxhall Zafira 1.6i Exclusiv 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/01/2009	Keys	2	CAP Clean	£520.00
Year	2009	Service history	Yes	CAP Average	£240.00
Mileage	108,370 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	MANUAL
Colour	BLUE	Last service date	30/03/2022	Gears	5
VIN	W0L0AHM759G023791	Last service miles	84,865		
Body Style	MPV	MOT Due	14/12/2025		

£50 ADDITIONAL FEE LAST SERVICE 30/3/22 @84865 MILES (12 SERVICES 2 MAIN DEALER) BOOK AND PRINT Stiff to get into gear

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5




4: Door nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel nsr
Chipped
1 To 5

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Poor Previous Repair
Poor Paint




12: Qtr Panel osr
Chipped
1 To 5

No Image




13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

14: Door osf
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Sill os
Rusted
Over 5mm



18: Wing osf
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK