

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Mini Hatchback 1.6 Cooper Pimlico 3dr

		-			
Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Sage State
		V5	Present		
Details					
Reg. date	23/03/2011	Keys	2	CAP Clean	£2,225.00
Year	2011	Service history	Yes	CAP Average	£1,800.00
Mileage	71,339 Miles Warranted	Service documents	Service Book	CAP Below	£1,350.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	MANUAL
Colour	BLUE	Last service date	25/09/2024	Gears	6
VIN	WMWSU32050T103132	Last service miles	70,726	Doors	3
Body Style	Hatchback	MOT Due	09/10/2025		

£100 ADDITIONAL FEE LAST SERVICE 25/9/24 @ 70726 MILES (12 SERVICES 7 MAIN DEALER) BOOK AND PRINT

Tyres			
NSF	MICHELIN	3.0mm	
NSR	MICHELIN	3.0mm	
OSF	MICHELIN	3.0mm	
OSR	MICHELIN	3.0mm	
Spare			

Features

- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- · Isofix child seat anchor points
- · Partial leather seat trim
- PAS Body coloured bumpers
- Front electric windows ٠
- Metallic Paint ٠
- Passenger airbag Alloy wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- ABS
- Central locking
- Steering wheel mounted controls
 Air conditioning
 Height adjustable drivers seat

- Drivers airbag
 Remote central locking

Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos





1: Bonnet Chipped 1 To 5

2: Bumper Front Scratched Over 100mm Thru Paint





3: Wheel nsf Scratched Over 50mm



Chipped UpTo 10mm



5: Door nsf Dented 2 Or Less UpTo 10mm



6: Qtr Panel nsr Dented Over 2 UpTo 10mm



7: Wheel nsr Scratched Over 50mm



8: Bumper Rear . Chipped **Multiple Chips**


No Image

No Image

9: Bumper Rear Scratched Over 25mm Not Thru Paint



11: Wheel osr Scratched Over 50mm






12: Qtr Panel osr Dented Between 10mm + 30mm



13: Door osf Scratched Over 25mm Thru Paint



14: Wheel osf Scratched Over 50mm

Interior

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK