



VEHICLE INSPECTION REPORT

NX64NUO

Land Rover Range Rover 4.4 SDV8 Autobiography 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/09/2014	Keys	2	CAP Clean	£12,850.00
Year	2014	Service history	Yes	CAP Average	£11,650.00
Mileage	101,277 Miles Warranted	Service documents	Printout	CAP Below	£10,450.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	AUTOMATIC
Colour	BLUE	Last service date	05/01/2021	Gears	8
VIN	SALGA2JE1EA187261	Last service miles	70,030		
Body Style	Estate	MOT Due	23/08/2025		

Hydraulic anti-roll pipes replaced 21/08/2024. Last Service: 05/01/2021 at 70030 miles. (4 services (3 main dealer))

Tyres

NSF	TRIANGLE	3.0mm
NSR	TRIANGLE	4.0mm
OSF	TRIANGLE	3.0mm
OSR	TRIANGLE	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm

No Image



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Bumper Rear
Chipped
Multiple Chips

No Image

No Image

13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Over 50mm

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
1 To 5

No Image

18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		