



# VEHICLE INSPECTION REPORT

**GX16MGV**

## Tesla Model S 235kW 70kWh 5dr [Nav]

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |

nama  
GRADE  
3

### Details

|           |                           |                 |                   |             |            |
|-----------|---------------------------|-----------------|-------------------|-------------|------------|
| Reg. date | 07/03/2016                | VIN             | 5YJSB7E15FF105043 | CAP Clean   | £11,150.00 |
| Year      | 2016                      | Body Style      | Hatchback         | CAP Average | £10,500.00 |
| Mileage   | 51,865 Miles<br>Warranted | Keys            | 1                 | CAP Below   | £9,850.00  |
| Fuel Type | Electric                  | Service history | None              | Doors       | 5          |
| Colour    | SILVER                    | MOT Due         | 17/03/2026        |             |            |

£65 ADDITIONAL FEE

### Tyres

|       |             |       |
|-------|-------------|-------|
| NSF   | MICHELIN    | 4.0mm |
| NSR   | CONTINENTAL | 5.0mm |
| OSF   | MICHELIN    | 4.0mm |
| OSR   | CONTINENTAL | 5.0mm |
| Spare |             |       |

## Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Scratched  
UpTo 25mm Thru Paint



3: Door osr  
Chipped  
1 To 5



4: Wheel osr  
Scratched  
Over 50mm



5: Wheel nsr  
Scratched  
Over 50mm



6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Not Thru Paint



8: Door nsf  
Chipped  
Edge Chip



9: Wheel nsf  
 Scratched  
 Over 50mm



10: Bumper Front  
 Scratched  
 Over 100mm Thru Paint

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

|                          |    |  |    |
|--------------------------|----|--|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |  |    |
| Roof / sunroof           | OK | Radio  | OK |
| Windows                  | OK | Steering                                       | OK |
| Sat nav                  | OK |  |    |