



VEHICLE INSPECTION REPORT

KO15OKG

Nissan Qashqai 1.6 dCi N-Tec+ 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2015	Keys	2	CAP Clean	£5,650.00
Year	2015	Service history	Yes	CAP Average	£4,900.00
Mileage	74,710 Miles Warranted	Service documents	Service Book	CAP Below	£4,175.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	CVT
Colour	SILVER	Last service date	22/01/2021	Gears	1
VIN	SJNFDAJ11U1433432	Last service miles	47,290	Doors	5
Body Style	Hatchback	MOT Due	28/06/2026		

£65 ADDITIONAL FEE. Last Service: 22/01/2021 at 47290 miles. (6 services (3 main dealer))

Tyres

NSF	AUTOGREEN	5.0mm
NSR	AUTOGREEN	5.0mm
OSF	AUTOGREEN	4.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Hole
UpTo 25mm



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5




5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Boot Lid
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
1 To 5

No Image

15: Door osr
Scratched
Over 25mm Not Thru Paint



16: Door osf
Chipped
1 To 5

No Image

17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		