



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV19KYU

Toyota Yaris 1.5 Hybrid Y20 5dr CVT [Bi-tone]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	21/05/2019	Body Style	Hatchback	MOT Due	20/05/2025
Year	2019	Keys	2	CAP Clean	£9,900.00
Mileage	44,969 Miles Warranted	Service history	Yes	CAP Average	£8,850.00
Fuel Type	Hybrid	Service documents	Printout	CAP Below	£7,800.00
Colour	White/black	Last service date	16/09/2022	Gearbox	AUTOMATIC
VIN	VNKKD3D320A592327	Last service miles	14,525	Doors	5

Last service 16/09/2022 @ 14525 miles (2 MAIN DEALER SERVICES) Possible brake issue

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	2.0mm
OSR	DAVANTI	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Audio remote control
- Front fog lights
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Digital radio
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels
- PAS
- Trip computer
- Electric door mirrors
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Chipped
Multiple Chips



3: Wing osf
Chipped
1 To 5



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Scratched
Over 25mm Not Thru Paint



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Scratched
Over 100mm Thru Paint

No Image

9: Boot Lid
Scratched
Over 25mm Not Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Over 30mm



12: Door nsr
Dented
Over 30mm

No Image

13: Door nsf
Scratched
Over 25mm Not Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK