



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**HK08KJX**

## Fiat Grande Punto 1.3 Multijet Dynamic 3dr [75]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	23/06/2008	Body Style	Hatchback	Last service miles	86,985
Year	2008	Keys	2	MOT Due	11/08/2025
Mileage	88,057 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	17	Doors	3
VIN	ZFA19900000431112	Last service date	07/08/2024		

£100 ADDITIONAL FEE. Last Service: 07/08/2024 at 86985 miles. (17 main dealer services ). Book & print.  
Heavy vibration at idle

### Tyres


NSF	KUMHO	3.0mm
NSR	KUMHO	3.0mm
OSF	KUMHO	3.0mm
OSR	KUMHO	3.0mm
Spare		

## Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



4: Wing nsf  
Chipped  
1 To 5



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Dented  
Over 30mm



7: Qtr Panel nsr  
Dented  
Over 30mm



8: Wheel nsr  
Scratched  
Over 50mm




9: Bumper Rear  
Poor Previous Repair  
Paint Flake



10: Boot Lid  
Dented  
Between 10mm + 30mm



11: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



12: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Door osf  
Dented  
Over 2 UpTo 10mm





15: Wing osf  
Chipped  
1 To 5

16: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK