



VEHICLE INSPECTION REPORT

LL08CXY

Ford Fiesta 1.4 Zetec Blue 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/06/2008	Keys	2	CAP Average	£200.00
Year	2008	Service history	Yes	CAP Below	£200.00
Mileage	132,500 Miles Warranted	Number of stamps	10	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	01/12/2023	Gears	5
Colour	BLACK	Last service miles	121,000	Doors	3
VIN	WF0DXXGAJD8K62741	MOT Due	13/09/2025		
Body Style	Hatchback	CAP Clean	£310.00		

Last Service: 01/12/2023 at 121000 miles. (10 services) Boot not working on button only key

Tyres


NSF	BUDGET	Damaged
NSR	BUDGET	5.0mm
OSF	GT RADIAL	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- 3x3 point rear seat belts
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- Radio/CD
- Climate control
- Metallic Paint
- Passenger airbag
- Alloy wheels

Photos







Condition Check



Damage Photos



1: Tyre nsf
Damaged
Replace



2: Tyre nsf
Damaged
Replace



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Scratched
25 to 100mm Thru Paint




5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Chipped
1 To 5




8: Wing nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Dented
Over 2 UpTo 10mm



10: Door nsf
Chipped
1 To 5



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Chipped
1 To 5



16: Wheel osr
Scratched
Over 50mm



17: Qtr Panel osr
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



19: Door osf
Dented
Over 2 UpTo 10mm




20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint




22: Wing osf
Chipped
1 To 5




23: Wing osf
Scratched
Over 25mm Not Thru Paint



24: Wheel osf
Scratched
Over 50mm



25: Tyre nsf
Damaged
Replace



26: Tyre nsf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK