

VEHICLE INSPECTION REPORT

RF66WOU

Volkswagen Sharan 2.0 TDI CR BlueMotion Tech 150 SE Nav 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/12/2016	VIN	WVWZZZ7NZHV218733	CAP Average	£4,750.00
Year	2016	Body Style	MPV	CAP Below	£4,025.00
Mileage	157,022 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
Fuel Type	Diesel	MOT Due	10/05/2026	Gears	6
Colour	BLUE	CAP Clean	£5,425.00		


Tyres

NSF	FALKEN	3.0mm
NSR	FALKEN	3.0mm
OSF	FALKEN	3.0mm
OSR	FALKEN	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Over 30mm



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image



9: Bumper Rear
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel osr
Dented
Over 30mm



12: Wheel osr
Scratched
Over 50mm




13: Door osr
Dented
Between 10mm + 30mm

No Image

14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Dented
Over 30mm



18: Wheel osf
Scratched
Over 50mm



19: Door Pad osf
Torn
UpTo 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK