

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Toyota Yaris 1.3 VVT-i TR 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		
		V5	TBC		
Details					
Reg. date	02/08/2008	VIN	VNKKL96360A320589	CAP Average	£1,025.00
Year	2008	Body Style	Hatchback	CAP Below	£625.00
Mileage	63,308 Miles	Keys	2	Gearbox	MANUAL
	Warranted	MOT Due	16/02/2026	Gears	5
Fuel Type	Petrol	CAP Clean	£1,425.00	Doors	5
Colour	SILVER				

1 rear headrest missing

Tyres			
NSF	FIRESTONE	6.0mm	
NSR	YOKOHAMA	5.0mm	
OSF	FIRESTONE	5.0mm	
OSR	YOKOHAMA	5.0mm	
Spare			

Features

- Rear wiper
 Air conditioning
 ABS
 Remote central locking
- Radio/CD
 Front electric windows
 Drivers airbag
 Cloth seat trim

- Body coloured bumpers
 Rear headrests
 Passenger airbag
 Alloy wheels

- Electric door mirrors
 Metallic Paint
 Central locking

Photos













Condition Check



Damage Photos






1: Bumper Rear Scratched 25 to 100mm Thru Paint

2: Wheel nsf Scratched Over 50mm





3: Bumper Front Scratched UpTo 25mm Thru Paint





5: Bonnet Chipped 1 To 5

Interior

Carpet Condition	
Seat Condition	

Average Average Upholstery Condition Odour

Chipped

UpTo 10mm

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK



EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	ОК		
Windows	OK	Radio	ОК
		Steering	OK