



VEHICLE INSPECTION REPORT

OU64VKH

Skoda Fabia 1.2 TSI 90 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	07/01/2015	VIN	TMBFM6NJ2FZ009208	CAP Average	£4,775.00
Year	2015	Body Style	Hatchback	CAP Below	£4,000.00
Mileage	24,256 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	25/01/2026	Gears	5
Colour	WHITE	CAP Clean	£5,550.00	Doors	5

£100 ADDITIONAL FEE.


Tyres


NSF	BRIDGESTONE	4.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm

No Image



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Bumper Rear
Chipped
Multiple Chips

No Image

No Image

13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Up To 50mm



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wing osf
Dented
Between 10mm + 30mm



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK