



VEHICLE INSPECTION REPORT

GV64HXS

Ford Focus 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

nama
GRADE
2

Details

Reg. date	30/01/2015	Keys	2	CAP Clean	£2,400.00
Year	2015	Service history	Yes	CAP Average	£1,925.00
Mileage	77,747 Miles Warranted	Service documents	Service Book	CAP Below	£1,500.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	RED	Last service date	12/04/2024	Gears	5
VIN	WF05XXGCC5FC00397	Last service miles	69,967	Doors	5
Body Style	Hatchback	MOT Due	13/04/2026		

LAST SERVICE 12/4/24 @ 69967 MILES (5 SERVICES 4 MAIN DEALER) BOOK
NO V5C


Tyres		
NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

3: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Wheel nsr
Scratched
Up To 50mm



6: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image

7: Door nsr
Scratched
Over 25mm Not Thru Paint

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image

9: Wing nsf
Scratched
Over 25mm Not Thru Paint



10: Wheel nsf
Scratched
Up To 50mm



11: Bumper Front
Chipped
Multiple Chips

No Image

12: Bumper Front
Scratched
Over 25mm Not Thru Paint




13: Bonnet
Chipped
1 To 5

No Image

14: Wing osf
Scratched
Over 25mm Not Thru Paint




15: Door osf
Dented
Over 2 UpTo 10mm



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Door osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK