

## **VEHICLE INSPECTION REPORT**

LR18NPN

### Toyota Prius 1.8 VVTi Business Edition Plus 5dr CVT

Inspection		Vehicle			nama
Serious Damage?	No	VAT	VAT Qualifying		Grape 3
		V5	Present	<u> </u>	
Details					
Reg. date	29/03/2018	Body Style	Hatchback	MOT Due	Expired
Year	2018	Service history	Yes	Gearbox	CVT
Mileage	64,549 Miles Warranted	Service documents	Printout	Gears	1
		Number of stamps	6	Doors	5
Fuel Type	Hybrid Electric	Last service date	05/11/2024		
Colour	RED	Last service miles	60,675		
VIN	JTDKB3FU003587149		,-		

Last Service - 05.11.2024 at 60675 miles (6 services)

Tyres	5
-------	---

NSF	PIRELLI	6.0mm
NSR	PIRELLI	6.0mm
OSF	MICHELIN	3.0mm
OSR	HANKOOK	5.0mm
Spare		

### **Features**

- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbagRemote central locking
- Cruise control
- Rear parking sensor Body coloured bumpers Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensorRear wiper
- Electric door mirrors
- Front electric windows
- ABSTyre pressure monitorAlloy wheels

- Navigation systemTelephone

- Telepriorie
  Air conditioning
  Rear electric windows
  Drivers airbag
  Central locking

#### **Photos**






















# **Condition Check**



## **Damage Photos**



1: Wheel osf Scratched Over 50mm



2: Wing osf Dented Between 10mm + 30mm



3: Door osf Scratched Over 25mm Not Thru Paint



4: Door osf Chipped Edge Chip



5: Door osf Dented Over 2 UpTo 10mm



6: Door osr Scratched Over 25mm Not Thru Paint



7: Qtr Panel osr Scratched Over 25mm Not Thru Paint




8: Wheel osr Scratched Over 50mm



9: Bumper Rear Scratched 25 to 100mm Thru Paint



10: Lamp osr Broken Replace



11: Qtr Panel nsr Poor Previous Repair Poor Paint



12: Wheel nsr Scratched Over 50mm



13: Door nsr Poor Previous Repair Poor Paint



14: Door nsf Poor Previous Repair Poor Paint



15: Wing nsf Poor Previous Repair Poor Paint



16: Wheel nsf Scratched Over 50mm



17: Bumper Front Scratched Over 25mm Not Thru Paint



18: Bonnet Chipped 1 To 5



19: Screen Front Chipped UpTo 10mm

#### Interior

**Carpet Condition Upholstery Condition** Average **Seat Condition** Odour Average

Average No

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK