



VEHICLE INSPECTION REPORT

RO64XCC

Mazda 6 2.2d SE-L Nav 4dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	31/10/2014	Keys	2	CAP Clean	£1,375.00
Year	2014	Service history	Yes	CAP Average	£980.00
Mileage	124,019 Miles Warranted	Service documents	Printout	CAP Below	£600.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	MANUAL
Colour	BLACK	Last service date	17/12/2021	Gears	6
VIN	JMZGJ621651185285	Last service miles	93,464	Doors	4
Body Style	Saloon	MOT Due	14/01/2026		

Last Service: 17/12/2021 at 93464 miles. (8 main dealer services)

Tyres

NSF	FALKEN	4.0mm
NSR	GOODYEAR	2.0mm
OSF	FALKEN	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image



3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

4: Wheel nsr
Scratched
Up To 50mm




5: Door nsr
Poor Previous Repair
Poor Paint

6: Door nsf
Poor Previous Repair
Poor Paint



7: Wing nsf
Dented
Over 30mm

8: Wheel nsf
Scratched
Over 50mm



9: Bonnet
Chipped
1 To 5

No Image

10: Bonnet
Scratched
Over 25mm Not Thru Paint



11: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Front
Scratched
Over 25mm Not Thru Paint

No Image

13: Wing osf
Scratched
Over 25mm Not Thru Paint



14: Wheel osf
Scratched
Over 50mm



15: Door osf
Chipped
1 To 5

No Image

16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Door osr
Chipped
1 To 5

No Image

18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Qtr Panel osr
Poor Previous Repair
Poor Paint



20: Wheel osr
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK