



VEHICLE INSPECTION REPORT

GV14NVB

Toyota Aygo 1.0 VVT-i X-Pression 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/07/2014	Keys	2	CAP Clean	£2,825.00
Year	2014	Service history	Yes	CAP Average	£2,325.00
Mileage	96,448 Miles Warranted	Service documents	Printout	CAP Below	£1,850.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	RED	Last service date	28/06/2024	Gears	5
VIN	JTDKGNEC80N010234	Last service miles	93,923	Doors	5
Body Style	Hatchback	MOT Due	01/07/2025		

Last Service: 28/06/2024 at 93923 miles. (8 main dealer services) High clutch

Tyres

NSF	FALKEN	3.0mm
NSR	CONTINENTAL	5.0mm
OSF	FALKEN	3.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Park assist camera
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Leather seat trim
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Other
N/A
N/A



4: Door osr
Chipped
1 To 5




5: Other
N/A
N/A



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint




7: Wheel osr
Scratched
Up To 50mm



8: Bumper Rear
Insecure
Action Required



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear
Chipped
1 To 5



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Up To 50mm



13: Door nsr
Dented
With Paint Damage



14: Other
N/A
N/A



15: Other
N/A
N/A



16: Door nsf
Scratched
Over 25mm Not Thru Paint



17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Poor Previous Repair
Paint Flake



19: Bonnet
Chipped
Multiple Chips



20: Roof
Dented
With Paint Damage



21: Carpets Front
Holed
UpTo 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK