



VEHICLE INSPECTION REPORT

GX15YWZ

Mazda 3 2.2d Sport Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/03/2015	Body Style	Hatchback	MOT Due	Expired
Year	2015	Keys	2	Gearbox	MANUAL
Mileage	111,784 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Diesel	Service documents	Printout	Doors	5
Colour	RED	Number of stamps	6		
VIN	JMZBM642611197128	Last service miles	76,162		

Last Service: Date not recorded at 76162 miles. (6 services (5 main dealer))

Tyres



NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	TRIANGLE	4.0mm
OSR	JINYU TIRES	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- PAS
- Audio remote control
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Torn
Over 3mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Poor Previous Repair
Poor Paint




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint




13: Boot Lid
Chipped
1 To 5




14: Wheel osr
Scratched
Over 50mm




15: Qtr Panel osr
Dented
Between 10mm + 30mm




16: Door osr
Chipped
1 To 5




17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Dented
Between 10mm + 30mm



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No