



VEHICLE INSPECTION REPORT

PO12WHA

Volkswagen Passat 2.0 TDI 170 Bluemotion Tech Sport 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date 26/03/2012

Year 2012

Mileage 108,603 Miles
Warranted

Fuel Type Diesel

Colour BLACK

VIN WVWZZZ3CZCE136378

Body Style Estate

Keys 2

Service history None

MOT Due 03/02/2026

CAP Clean £2,900.00

CAP Average £2,425.00

CAP Below £1,950.00

Gearbox MANUAL

Gears 6

£65 ADDITIONAL FEE. Reverse light bulb check on dash and airbag light on

Tyres

NSF FALKEN 5.0mm

NSR FALKEN 5.0mm

OSF FALKEN 4.0mm


OSR HANKOOK 4.0mm


Spare

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Torn
Over 3mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
Multiple Chips




4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Wing nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Chipped
1 To 5

No Image

9: Door nsf
Scratched
Over 25mm Not Thru Paint




10: Door nsr
Chipped
1 To 5

No Image

11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image

14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Bumper Rear
Scratched
25 to 100mm Thru Paint




16: Bumper Rear
Scratched
Over 25mm Not Thru Paint



17: Boot Lid
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



20: Wheel osr
Scratched
Over 50mm



21: Door osr
Chipped
1 To 5




22: Door osr
Scratched
Over 25mm Not Thru Paint



23: Door osf
Chipped
Multiple Chips



24: Wing osf
Scratched
Over 25mm Thru Paint



25: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK