



# VEHICLE INSPECTION REPORT

**BK59XUX**

## Volkswagen Polo 1.2 70 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
3

### Details

Reg. date	08/10/2009	Keys	2	CAP Clean	£2,100.00
Year	2009	Service history	Yes	CAP Average	£1,650.00
Mileage	111,229 Miles Warranted	Service documents	Service Book	CAP Below	£1,225.00
Fuel Type	Petrol	Number of stamps	11	Gearbox	MANUAL
Colour	RED	Last service date	07/10/2020	Gears	5
VIN	WVWZZZ6RZAU000300	Last service miles	90,717	Doors	5
Body Style	Hatchback	MOT Due	11/11/2025		

£65 ADDITIONAL FEE. LAST SERVICE 7/10/20 @ 90717 MILES (11 SERVICES 7 MAIN DEALER) BOOK

### Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Poor Previous Repair  
Poor Colour





3: Wheel nsf  
Scratched  
Over 50mm

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

No Image

5: Door nsf  
Scratched  
Over 25mm Not Thru Paint

No Image

6: Door nsr  
Scratched  
Over 25mm Not Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm

No Image

8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image

10: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image

11: Boot Lid  
Scratched  
Over 25mm Not Thru Paint

No Image

12: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



13: Wheel osr  
Scratched  
Over 50mm

No Image

14: Door osr  
Scratched  
Over 25mm Not Thru Paint



15: Door osf  
Dented  
2 Or Less UpTo 10mm



16: Wing osf  
Dented  
Over 30mm



17: Screen Front  
Chipped  
UpTo 10mm



18: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

### Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK