



# VEHICLE INSPECTION REPORT

**FT12KJZ**

## Volkswagen Polo 1.2 60 Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	04/05/2012	Keys	2	CAP Clean	£2,875.00
Year	2012	Service history	Yes	CAP Average	£2,400.00
Mileage	93,320 Miles Warranted	Service documents	Service Book	CAP Below	£1,925.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	MANUAL
Colour	BLACK	Last service date	22/01/2025	Gears	5
VIN	WVWZZZ6RZCU051843	Last service miles	92,000	Doors	5
Body Style	Hatchback	MOT Due	30/01/2026		

£65 ADDITIONAL FEE. LAST SERVICE 22/1/25 @ 92000 MILES (12 SERVICES) BOOK AND PRINT


### Tyres

NSF	VREDESTEIN	4.0mm
NSR	GOODYEAR	4.0mm
OSF	VREDESTEIN	3.0mm
OSR	GOODYEAR	4.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wing nsf  
Dented  
With Paint Damage



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Dented  
Over 2 UpTo 10mm

No Image



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Chipped  
1 To 5

No Image



9: Door nsf  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image


13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image

14: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



15: Qtr Panel osr  
Dented  
Between 10mm + 30mm



16: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint




17: Wheel osr  
Scratched  
Over 50mm



18: Door osr  
Dented  
Over 30mm



19: Door osf  
Chipped  
1 To 5



20: Door osf  
Scratched  
Over 25mm Not Thru Paint





21: Wheel osf  
Scratched  
Over 50mm



22: Wing osf  
Chipped  
1 To 5

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK