



VEHICLE INSPECTION REPORT

WN68SXB

Mitsubishi L200 Double Cab DI-D 178 Barbarian 4WD Auto

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
3

Details

Reg. date 01/10/2018

Year 2018

Mileage 89,260 Miles
Warranted

Fuel Type Diesel

Colour BLUE

VIN MMCJYKL10JH019740

Body Style Pick-up

MOT Due 21/08/2025

CAP Clean £11,100.00

CAP Average £9,575.00

CAP Below £7,475.00

Gearbox AUTOMATIC

Gears 5

Doors 5

£65 ADDITIONAL FEE.

Tyres

NSF MICHELIN 3.0mm

NSR MICHELIN 3.0mm

OSF MICHELIN 3.0mm

OSR MICHELIN 3.0mm

Spare

Features


- Bluetooth connection
- Auxiliary input socket
- Rear electric windows
- Central locking
- Cruise control
- Digital radio
- Metallic Paint
- Leather seat trim
- Heated front seat
- Air conditioning
- Drivers airbag
- Park assist camera
- Front electric windows
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
Multiple Chips



8: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Up To 50mm



11: Boot Lid
Scratched
Up To 25mm Thru Paint

No Image

12: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image




13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Scratched
UpTo 25mm Thru Paint




16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wing osf
Scratched
Over 25mm Not Thru Paint



20: Wheel osf
Scratched
Up To 50mm



21: Screen Front
Chipped
UpTo 10mm

22: Qtr Panel osr
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK