



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

ST15HGG

BMW 4 Series 435d xDrive M Sport 5dr Auto [Professional Media]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	30/04/2015	VIN	WBA4G12030D966834	CAP Below	£9,125.00
Year	2015	Body Style	Coupe	Gearbox	AUTOMATIC
Mileage	68,987 Miles Warranted	Keys	2	Gears	8
Fuel Type	Diesel	CAP Clean	£11,350.00		
Colour	BLACK	CAP Average	£10,250.00		

£65 ADDITIONAL FEE.

Tyres

NSF	LAUFENN	3.0mm
NSR	BUDGET	4.0mm
OSF	LAUFENN	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- PAS
- Digital radio
- Climate control
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



10: Bumper Rear
Chipped
Multiple Chips




11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Door osr
Chipped
1 To 5

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint

No Image

17: Door osf
Scratched
Over 25mm Not Thru Paint

No Image

18: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK