

VEHICLE INSPECTION REPORT



Land Rover Range Rover Evoque 2.2 SD4 Dynamic 5dr Auto [Lux Pack]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present		
Details					
Reg. date	08/09/2011	Body Style	Estate	Last service miles	89,409
Year	2011	Keys	2	MOT Due	Expired
Mileage	91,831 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
		Service documents	Service Book	Gears	6
Fuel Type	Diesel	Number of stamps	13		
Colour	WHITE	Last service date	05/09/2024		
VIN	SALVA2AE7CH603731				

£65 ADDITIONAL FEE. LAST SERVICE 05-09-2024 @89409 MILES (13 SERVICES) Reverse camera not working, Air bag light on

T	·y	r	е	S

NSF	MICHELIN	4.0mm	
NSR	MICHELIN	3.0mm	
OSF	MICHELIN	4.0mm	
OSR	MICHELIN	3.0mm	
Spare			

Features

- Bluetooth connection
- PAS
- Audio remote control
- · Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Front head restraints
- Rear headrests
- Drivers airbag Traction control
- Alloy wheels

- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- · Central locking

- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable drivers seat Electrically adjustable passenger seat
 - Rear armrest
 - 3x3 point rear seat belts
 - Passenger airbag
 - Remote central locking

Photos






















Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Chipped Multiple Chips

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Over 50mm

No Image

5: Wing nsf Scratched Over 25mm Not Thru Paint



6: Door nsf Chipped 1 To 5

No Image

7: Door nsf Scratched Over 25mm Not Thru Paint

No Image

8: Door nsr Scratched Over 25mm Not Thru Paint



9: Wheel nsr Scratched Up To 50mm

No Image

10: Qtr Panel nsrScratchedOver 25mm Not Thru Paint



11: Bumper Rear ChippedMultiple Chips

No Image

12: Bumper Rear Scratched Over 25mm Not Thru Paint

No Image

13: Boot Lid Scratched Over 25mm Not Thru Paint

No Image

14: Qtr Panel osrScratchedOver 25mm Not Thru Paint



15: Wheel osr Scratched Up To 50mm



16: Door osr Dented Between 10mm + 30mm

No Image

17: Door osr Scratched Over 25mm Not Thru Paint



18: Door osfChipped1 To 5

No Image

19: Door osf Scratched Over 25mm Not Thru Paint

No Image

20: Wing osf Scratched Over 25mm Not Thru Paint



21: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	ОК	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		