

## **VEHICLE INSPECTION REPORT**

**GF71WJD** 

### **Tesla Model 3 Standard Plus 4dr Auto**

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	TBC		
Details					
Reg. date	27/11/2021	VIN	LRW3F7FJ4MC388405	CAP Average	£14,350.00
Year	2021	Body Style	Saloon	CAP Below	£13,050.00
Mileage	27,656 Miles Warranted	Keys	2	Doors	4
		MOT Due	26/11/2025		
Fuel Type	Electric	CAP Clean	£15,650.00		
Colour	GREY				

#### £65 ADDITIONAL FEE.

_	-			
	1/	r	0	c
	v		c	J

NSF	MICHELIN	4.0mm	
NSR	MICHELIN	4.0mm	
OSF	MICHELIN	4.0mm	
OSR	MICHELIN	4.0mm	
Spare		-	

### **Features**

- Bluetooth connection
  Navigation system
- Steering wheel mounted controls
  Electric door mirrors
  Fixed panoramic glas

- Front head restraints
- Rear headrestsDrivers airbag
- Central locking

- · Cruise control
- Park assist camera
- Fixed panoramic glass roof
- Electrically adjustable drivers seat Electrically adjustable passenger Front armrest seat
  - Height adjustable drivers seat

  - Metallic PaintIsofix child seat anchor points
  - · Leather seat trim
- Front parking sensorPAS

- Digital radioAir conditioning
- Rear armrest
- 3x3 point rear seat beltsPassenger airbag
- Alloy wheels

- Heated front seat
- Rear parking sensorBody coloured bumpersClimate control
- Front electric windows
- · Rear electric windows
- ABS
  Traction control

### **Photos**






















## **Condition Check**



## **Damage Photos**



1: Bonnet Chipped 1 To 5




2: Bumper Front Chipped Multiple Chips

## No Image

# No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint





5: Door nsf Chipped 1 To 5

# No Image

6: Door nsf Scratched Over 25mm Not Thru Paint

# No Image

# No Image

7: Door nsr Scratched Over 25mm Not Thru Paint

8: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



9: Bumper Rear Chipped Multiple Chips

# No Image

10: Bumper RearScratchedOver 25mm Not Thru Paint



11: Door osrChipped1 To 5

# No Image

12: Door osf Scratched Over 25mm Not Thru Paint

# No Image

13: Wing osf Scratched Over 25mm Not Thru Paint

#### Interior

**Carpet Condition Seat Condition** 

Average Average **Upholstery Condition Odour** 

Average No

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Brakes	OK	Gearbox 1st and Reverse Test	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
EME light illuminated	UK	On warning fight fluthinated	UK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		