

## **VEHICLE INSPECTION REPORT**

YS23NVC

### Nissan Qashqai 1.5 E-Power N-Connecta 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 crape
		V5	TBC	•	
Details					
Reg. date	12/05/2023	VIN	SJNTBAJ12U1277229	CAP Average	£18,650.00
Year	2023	Body Style	Hatchback	CAP Below	£17,250.00
Mileage	21,095 Miles	Keys	1	Gearbox	AUTOMATIC
	Warranted	MOT Due	11/05/2026	Gears	5
Fuel Type	Hybrid Electric	CAP Clean	£20,050.00	Doors	 5
Colour	RED		·		

#### £65 ADDITIONAL FEE.

_	-			
	1/	r	0	c
	v		ᆫ	J

NSF	PIRELLI	5.0mm	
NSR	PIRELLI	5.0mm	
OSF	PIRELLI	4.0mm	
OSR	BRIDGESTONE	5.0mm	_
Spare			

### **Features**

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls •
- Electric door mirrors
- · Front electric windows
- Rear electric windows

- ABSSide airbagsRemote central locking
- · Cruise control
- PAS
- Audio remote control
- Air conditioning
  Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Cloth seat trim

- Front parking sensor

- Front parking sensor
  Rear parking sensor
  Digital radio
  Climate control
  Height adjustable drivers seat
  Metallic Paint
  Isofix child seat anchor points
  Tyre pressure monitor
  Allov wheels

- Alloy wheels


- Navigation system
- Rear wiper
- Body coloured bumpers Front armrest
- Rear armrest
- 3x3 point rear seat beltsPassenger airbagCentral locking

### **Photos**












# **Condition Check**



## **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint

# No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Up To 50mm

# No Image

5: Door nsf Scratched Over 25mm Not Thru Paint



7: Wheel nsr Scratched Up To 50mm

# No Image

6: Door nsr Scratched Over 25mm Not Thru Paint




8: Bumper Rear Chipped Multiple Chips

# No Image

# No Image

9: Bumper Rear Scratched Over 25mm Not Thru Paint





11: Wheel osf Scratched Up To 50mm

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	ОК
Sat nav	OK	Steering	OK