

VEHICLE INSPECTION REPORT

RK13VNJ

Audi A5 2.0 TDI 177 SE 5dr [5 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	14/03/2013	VIN	WAUZZZ8T6DA058465	CAP Average	£3,650.00
Year	2013	Body Style	Hatchback	CAP Below	£3,200.00
Mileage	93,443 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	09/02/2026	Gears	6
Colour	BLUE	CAP Clean	£4,100.00	Doors	5


Tyres

NSF	FIRESTONE	2.0mm
NSR	HANKOOK	3.0mm
OSF	FIRESTONE	2.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage




5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Chipped
Multiple Chips

No Image

11: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

12: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




16: Door osr
Chipped
1 To 5



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Dented
2 Or Less UpTo 10mm



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK