



VEHICLE INSPECTION REPORT

GU61RYO

Toyota Verso-S 1.33 Dual VVT-i TR 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|------------|---------------------------|--------------------|------------|-------------|-----------|
| Reg. date | 01/09/2011 | Keys | 2 | CAP Clean | £2,500.00 |
| Year | 2011 | Service history | Yes | CAP Average | £2,000.00 |
| Mileage | 57,449 Miles Warranted | Service documents | Printout | CAP Below | £1,550.00 |
| Fuel Type | Petrol | Number of stamps | 1 | Gearbox | MANUAL |
| Colour | SILVER | Last service date | 16/10/2012 | Gears | 6 |
| VIN | JTDKJ3C3501006173 | Last service miles | 3,082 | | |
| Body Style | MPV | MOT Due | 04/09/2025 | | |

£100 ADDITIONAL FEE LAST SERVICE 16/10/12 @ 3082 MILES (1 MAIN DEALER SERVICE) PRINT P

Tyres

| | | |
|-------|--------|-------|
| NSF | BUDGET | Worn |
| NSR | BUDGET | 5.0mm |
| OSF | BUDGET | 2.0mm |
| OSR | BUDGET | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
Between 10mm + 30mm



4: Door nsf
Dented
With Paint Damage



5: Door nsr
Chipped
1 To 5



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint

No Image



9: Boot Lid
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel osr
Poor Previous Repair
Poor Paint



11: Door osr
Chipped
1 To 5

No Image

12: Door osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Dented
Between 10mm + 30mm

No Image

14: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



15: Wing osf
Scratched
Over 25mm Not Thru Paint

16: Seat Base Cover osf
Torn
UpTo 3mm

No Image

17: Tyre nsf
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|---------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |