



# VEHICLE INSPECTION REPORT

**LX65UXB**

## Vauxhall Mokka 1.4T SE 5dr Auto

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

### Details

Reg. date 22/09/2015

Year 2015

Mileage 147,809 Miles  
Warranted

Fuel Type Petrol

Colour BLACK

VIN W0LJD7E82FB254059

Body Style Hatchback

Keys 2

Service history Yes

Number of stamps 12

Last service date 12/06/2025

Last service miles 147,658

MOT Due 05/07/2026

Gearbox AUTOMATIC

Gears 6

Doors 5

£100 ADDITIONAL FEE

### Tyres

NSF ROTALLA 4.0mm

NSR BUDGET 5.0mm

OSF ROTALLA 4.0mm

OSR RAPID 5.0mm

Spare

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Chipped  
1 To 5

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door nsf  
Chipped  
1 To 5

No Image

6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Wheel nsf  
Scratched  
Over 50mm

No Image

8: Door nsr  
Scratched  
Over 25mm Not Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm

No Image

10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint

No Image

12: Boot Lid  
Scratched  
Over 25mm Not Thru Paint

No Image

13: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



14: Wheel osr  
Scratched  
Over 50mm





15: Door osr  
Chipped  
1 To 5



16: Door osr  
Scratched  
Over 25mm Not Thru Paint



17: Door osf  
Chipped  
1 To 5



18: Wing osf  
Poor Previous Repair  
Poor Paint



19: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK