

#### 46 Brampton Road Eastbourne BN22 9BN 01323 520295 | no-reply@ebca.co.uk

**VEHICLE INSPECTION REPORT** 



# Vauxhall Corsa 1.2i 16V Design 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present		
Details					
Reg. date	28/09/2007	Keys	2	CAP Clean	£450.00
Year	2007	Service history	Yes	CAP Average	£200.00
Mileage	87,865 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
		Number of stamps	13	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	05/10/2022	Gears	5
Colour	BLACK	Last service miles	81,357	Doors	5
VIN	W0L0SDL6874445934	MOT Due	10/10/2025		
Body Style	Hatchback				

# LAST SERVICE 5/10/22 @ 81357 MILES (13 SERVICES 5 MAIN DEALER) BOOK AND PRINT Drivers door handle missing inside car

Tyres			
NSF	RAPID	3.0mm	
NSR	SUNNY	3.0mm	
OSF	RAPID	4.0mm	
OSR	SUNNY	4.0mm	
Spare			

•

## Features

Remote central locking

Rear wiperAir conditioning

ABS

- Radio/CD
  - Front electric windows
  - Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbagLeather seat trim
- Electric door mirrors
- Metallic Paint
- Central locking
- Alloy wheels

#### Photos
















# **Condition Check**



### **Damage Photos**







2: Seat Base Cover osf Holed Over 3mm





3: Wheel osf Scratched Over 50mm

4: Door osf Poor Previous Repair Poor Paint



5: Door osr Poor Previous Repair Poor Paint



6: B Post os Poor Previous Repair Poor Paint




7: C Post os Poor Previous Repair Poor Paint



8: Wheel osr Scratched Up To 50mm



9: Other N/A N/A





11: Bumper Rear Chipped 1 To 5



12: Wheel nsr Scratched Up To 50mm



13: Door nsr Scratched Over 25mm Not Thru Paint




14: Door nsf Scratched Over 25mm Not Thru Paint





15: Wing nsf Poor Previous Repair Poor Paint



16: Bumper Front Poor Previous Repair Poor Paint



17: Wheel nsf Scratched Over 50mm

18: Bonnet Poor Previous Repair Poor Paint



19: Roof Poor Previous Repair Poor Paint

Interior

Eastbourne Car Auctions

#### Vehicle Inspection Report

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK