



VEHICLE INSPECTION REPORT

HY67XUM

Dacia Sandero 0.9 TCe Laureate 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
2

Details

Reg. date 26/09/2017

Year 2017

Mileage 93,790 Miles
Warranted

Fuel Type Petrol

Colour BLUE

VIN UU15SDL1558476833

Body Style Hatchback

Keys 1

Service history Yes

Number of stamps 3

Last service date 24/02/2020

Last service miles 87,102

MOT Due 19/02/2026

CAP Clean £2,350.00

CAP Average £1,925.00

CAP Below £1,500.00

Gearbox MANUAL

Gears 5

Doors 5

Tapping noise from engine

Tyres

NSF GT RADIAL 4.0mm

NSR GT RADIAL 5.0mm

OSF GT RADIAL 4.0mm

OSR GT RADIAL 5.0mm

Spare

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front head restraints
- ABS
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Chipped
1 To 5

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Dented
Between 10mm + 30mm

No Image

11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image


14: Bonnet
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Dented
Between 10mm + 30mm

No Image

16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Door osr
Dented
Between 10mm + 30mm

No Image


18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Door osf
Dented
Between 10mm + 30mm

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Wing osf
Dented
Between 10mm + 30mm

22: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK