

VEHICLE INSPECTION REPORT

GM65MKP

Vauxhall Adam 1.2i Jam 3dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	22/01/2016	Keys	1	CAP Clean	£2,875.00
Year	2016	Service history	Yes	CAP Average	£2,400.00
Mileage	73,603 Miles Warranted	Service documents	Service Book	CAP Below	£1,925.00
		Number of stamps	7	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	04/12/2024	Gears	5
Colour	RED	Last service miles	67.072	Doors	3
VIN	W0L0MAP08F6109105		08/12/2025		
Body Style	Hatchback		,-,		

£65 ADDITIONAL FEE LAST SERVICE 4/12/24 @ 67072 MILES (7 SERVICES 4 MAIN DEALER) BOOK Slight tapping noise

Tyres	
NCE	

NSF	BUDGET	2.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare	'	

Features


- · Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front head restraints
- Central locking
- Cruise control
- Audio remote control
- Air conditioning Height adjustable drivers seat
- Drivers airbag
- Remote central locking
- PAS
- · Digital radio
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Traction control
- Alloy wheels

Photos












Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Dented With Paint Damage



5: Door nsf Dented Over 2 UpTo 10mm

No Image

6: Door nsf Scratched Over 25mm Not Thru Paint



7: Qtr Panel nsr Dented Over 2 UpTo 10mm

No Image

8: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



9: Wheel nsr Scratched Over 50mm



10: Bumper RearScratched25 to 100mm Thru Paint

No Image

11: Bumper Rear Scratched Over 25mm Not Thru Paint



12: Wheel osr Scratched Over 50mm



13: Qtr Panel osr Scratched Over 25mm Thru Paint



14: Door osf Scratched Over 25mm Thru Paint



15: Wing osfChippedMultiple Chips



16: Wheel osf Scratched Up To 50mm



17: Roof Chipped 1 To 5

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OI	Gearbox 1st and Reverse Test	OK
Brakes OI	Clutch Slip Test from Static	OK
Parking Brake OI	Gearbox Static Gear Selection (engine running)	OK
	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK