

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Mercedes-Benz GLA GLA 200 AMG Line Executive 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		
		V5	TBC	-	
Details					
Reg. date	02/07/2021	VIN	W1N2477872J305998	CAP Average	£20,150.00
Year	2021	Body Style	Hatchback	CAP Below	£18,750.00
Mileage	42,407 Miles Warranted	Keys	2	Doors	5
		MOT Due	21/04/2026		
Fuel Type	Petrol	CAP Clean	£21,550.00	-	
Colour	GREY		,	-	

£65 ADDITIONAL FEE

Tyres			
NSF	BRIDGESTONE	4.0mm	
NSR	CONTINENTAL	3.0mm	
OSF	BRIDGESTONE	4.0mm	
OSR	BRIDGESTONE	5.0mm	
Spare			

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers • Front electric windows
- Rear electric windows
- ABS
- Traction control
- · Alloy wheels

- · Cruise control ٠
- Park assist camera Steering wheel mounted controls Electric door mirrors ٠
- ٠
- Front head restraints ٠ •
- Rear headrests
- Drivers airbagCentral locking
- · Front parking sensor
- PAS
- Audio remote control Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
 Remote central locking
- · Heated front seat
- Rear parking sensor Digital radio Front armrest

- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
 Partial leather seat trim

Photos


















Condition Check



Damage Photos







2: Bumper Front Scratched 25 to 100mm Thru Paint

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Up To 50mm



No Image

6: Door nsf Scratched Over 25mm Not Thru Paint





7: Door nsr Scratched UpTo 25mm Thru Paint

No Image

8: Door nsr Scratched Over 25mm Not Thru Paint





9: Wheel nsr Scratched Up To 50mm

10: Bumper Rear Chipped Multiple Chips

No Image

No Image

11: Bumper Rear Scratched Over 25mm Not Thru Paint 12: Boot Lid Scratched Over 25mm Not Thru Paint

No Image

No Image

13: Qtr Panel osr Scratched Over 25mm Not Thru Paint 14: Door osr Scratched Over 25mm Not Thru Paint



No Image

15: Door osf Chipped 1 To 5



16: Door osf Scratched Over 25mm Not Thru Paint

17: Wheel osf Scratched Up To 50mm

Interior

Carpet Condition Seat Condition Average Average Upholstery Condition Odour Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK